

Bob van Evelingen



Power Supply
B10E


www.programmabob.nl

Megger.
AUTHORISED DISTRIBUTOR



B10E
Power Supply Unit
for Breaker Testing

APPLICATION EXAMPLE



Testing the minimum trip voltage of a breaker

1. Connect Power Supply Unit B10E to the breaker's opening circuit and to the spring-charging motor.
2. Set the desired test voltage using the variac.
3. Activate the trip pulse switch.
4. Repeat steps 2-3 at a higher voltage if the circuit breaker does not trip.







